Work Orde Tuesday, April 12												Page 1
	D3535-11			Accept					Setup	Start		
Revision ID:	***									Stop		
	Wearshoe		1 (18814) (1811	ITE						отор		
	4/12/2011	Start Qty: 8.00			Cust Item	ID:						
Required Date:	4/15/2011	Req'd Qty: 8.00			Customer:							
Reference:							_		-	C44	1 18 5	EEEE
Approvals:	Process Pla	nn:	Date: //-04	L/2_Tooling:	D	ate:		ł	Run	Start		
	QC:		Date:	SPC (Y/N):	D	ate:	or consumption of the same			Stop		
Sequence ID/ Work Center ID)	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rejo Qty		Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr										
D3535	Rev	В		e te								
100				0.00								
		FLOW WATER JET						BI	1-4-	19		
Waterjet		Memo	D D2424 CD	0.00 g Rev: \$□Prog Rev: -	2							
FLOW CNC Waterje	et .		per Dwg D3535 □Dw f necessary	g Rev: D	<u>S</u> 02-	,			-			(0)
110		QC2- Inspect parts of	ff machine FAI/FAIB	0.00								
QC		Memo		0.00				1811	-4-16	î		
Quality Control			•				•					
												•
120		QC8- Inspect parts -	second check	0.00 Such	٠/١٩			(22)	`			
QC Ouality Control		Memo	;	0.00	~ ((-40	/			

. .

W/O:	•		WO	RK ORDER CHANG	ES		••••		
DATE	STEP	PRC	OCEDURE CHAN		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									,
						-			
			·						
Part No	•	PAR #:	Fault Categ	jory:	_ NCR: Yes	No DQA	\:	_ Date: _	
Resolution:			Disposition);	_ QA: N/C Cld	sed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCR)			
ÒATE	CTED	Description of NC			ion B	Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
			·						
•							,		
		,							
,									

	,								

Work Orde Tuesday, April 1.	•									Pa	ge 2
Revision ID:	D3535-11 Wearshoe			Accept				Setup	Start Stop		
	4/12/2011	Start Qty: 8.00 Req'd Qty: 8.00			Cust Item II Customer:) :			•		
Approvals:	Process Pla	n:	Date:	Tooling: SPC (Y/N):	Da			Run	Start Stop		
Sequence ID/ Work Center ID 130 Brake NC Brake NC			rake as per Dwg D3535 us Dwg D3535 using Jig DT				Plan Ac Code Qt		-	Reject Insp. Number Stam	
QC Quality Control		QC5- Inspect part comple Memo	eteness to step on W/O	0.00 C W	osluo		_6	(40)	· -		·

0.00

0.00

10 BR 11-4-21.

Grey Sandtex(Ref:4.3.5.6) per QS1005 4.3

150

Powdercoat

Powder Coating

W/O:			V	VORK ORDER CHANG	ES					2
DATE	STEP	PRO	CEDURE CH	IANGE	B	,	Date G	ty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			•				-			
_										
Dort No.	_	DAD #-	Facilit Oa	A	NOD.	/aa N	In DOA:		Data	
Part No		esolution:								
NCR:				DER NON-CONFORMA						
DATE	STEP	Description of NC		Corrective Action Section		0	Verificati		Approval	Approval
DAIL	JILF	Section A	Initial Action Description Chief Eng Chief Eng			gn & Date	Section C		Chief Eng	QC Inspector
					·					
		· .								
							·			

Work Order ID 68362 Tuesday, April 12, 2011 10:12:23 AM Item ID: D3535-11 Accept Setup Start **Revision ID:** Stop Item Name: Wearshoe 4/12/2011 Start Qty: 8.00 **Start Date: Cust Item ID:** Req'd Qty: 8.00 Required Date: 4/15/2011 **Customer:** Reference: Run Start Date: Tooling: Process Plan: Approvals: Date: Stop Date: QC: SPC (Y/N): Date: Sequence ID/ Operation Reject Tool ID Tool # Plan Set Up/ Accept Reject Work Center ID Description Qty Qty Code Number Run Hours 160 QC3- Inspect Part Finish 0.00 QC 0.00 Memo Quality Control 0.00

170

Packaging Packaging

Identify as per dwg & Stock Location:

Memo

0.00

Bl H- 4-21

Insp.

Stamp

180

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

mus 11-04-21

Page 3

W/O:			V	ORK ORDER CHANG	GES					ž
DATE	STEP	PRO	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					,					
				,						
		÷								
						`				
Part No	:	PAR #:	Fault Ca	tegory:	NCR	: Yes N	lo DQA:		Date:	
	Resolution: Disposition:									
NCR:		. , v	ORK OR	DER NON-CONFORM	IANCE	(NCR)	I			
DATE	STEP	Description of NC		Corrective Action Section B			Verifica	tion	Approval	Approval
DATE	SIEP	Section A	Initial Action Description Chief Eng Chief Eng			Sign & Date	Section C		Chief Eng	QC Inspector
_									_	
	1	A Company of the Comp								

Picklist Print

Tuesday, April 12, 2011 10:12:29 AM

Work Order ID: 68362

Parent Item:

D3535-11

Parent Item Name:

Wearshoe



Start Date: 4/12/2011

Required Date: 4/15/2011

Page 1

Start Qty: 8.00

Required Qty: 8.00

Comments:

IPP Rev:A

New Issue 07-02-15 JLM

IPP Rev:B As per Rev B 07-08-31 JLM

Verified By:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304S20GA		Purchased	No			100	sf	67.4000	0.7015	5.907368	7		_
304/316, 040 Sheet										181	1-4-19		

<u>Location</u>	Loc Qty	Loc Code
MAT020	67.4	
116437	25.4	
116623	42	

	•								
W/O:			W	ORK ORDER CHANGE	S				,
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·							
		·							
Part No	:	PAR #:	Fault Ca	tegory:	NCR: Yes	No DQ	A :	Date: _	
	Re	esolution:	Disposit	ion:	QA: N/C C	losed:		Date: _	
NCR:		V	WORK ORI	DER NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC	Corrective Action Section		Verific	ication Approval		Approval	
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	on C	Chief Eng	QC Inspector
•								·	
								·	


DART AEROSPACE LTD	Work Order: U834	2_
Description: Wearshoe	Part Number: D3535-1	1
Inspection Dwg: D3535 Rev: B	Page 1 of	F 1

	FIRST ARTICLE INSPECTION CHECKLIST											
	X	F	irst Article		rotot	уре						
Drawing Dimension	Tolerance		Actual Dimension	Accept	Rejec	Method of Inspection	C	Comments				
5.00	+/-0.010		5,60	Q		T 1301						
8.00	+/-0.010		8,00	p		T						
14.00	+/-0.010		14,00	7		1						
21.150	+/-0.010		21.150			7						
26.650	+/-0.010		76.650	X		7						
5.650	+/-0.010		5650	×		7						
Ø0.188	+0.005/-0.001		.192	*		V 1302						
0.300	+/-0.010		,307	>		V						
0.300	+/-0.010		.329	2		V						
0.038	+/-0.010		, 034)		Υ						
Measured by:	B	Aud	dited by:		Р	rototype Appro	val:	N/A				
Date:	11-4-19		Date: [[]	04/17	Date: N/A			N/A				
	T 61 -			•		Desired	1	Ι Δ				

Rev	Date	Change		Revised by	Approved
Α	09.05.07	New Issue	,	KJ/DD %	
•	***************************************		· / / · · · · · · · · · · · · · · · · ·		

111/0	•	учинининин на	W/0	DI ODDED OUANG	· ·					
W/O:			WO	RK ORDER CHANG	iES			,,		·
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				,						
							è			
Part No		PAR #:	gory:	_ NCR	: Yes	No DQ	\ :	Date:		
	Re	esolution:	Disposition	n:	QA:	N/C CId	sed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE	(NCR)		. ,	
		Description of NC	Corrective Action Section B			Sign &	Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Initial Action Description Chief Eng Chief Eng			Section		Chief Eng	QC Inspecto
,										

			-							
	1									



	-										
W/O:			W	ORK ORDER C	HANGES					*	
DATE	STEP	PRO	CEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
										·	
					•						
						The state of the s		-	-		
Part No	•	PAR #:	Fault Cate	NO	CR: Yes	No DQ	A:	Date:			
	Re	solution:	Disposition:			A: N/C Clo	: N/C Closed:			Date:	
NCR:		`	WORK ORD	ER NON-CONI	FORMANC	E (NCR)				
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verific		ation	Approval	Approval	
			Initial Chief Eng	Action Desc Chief En	eription _.	Sign & Date	Secti	on C	Chief Eng	QC Inspector	
•										·	
•	,						\$				
				. 							
			~								
									• .		
								*			